



A Govt. of Maharashtra Undertaking)

CIN:U40109MH2005SGC153645

Office of the Superintending Engineer, 2/3 "Deepashree" Navghar(E), Vasai Rd.

Phone : 95250 - 2393373, 2391096 (O), 2391144 (P), E-mail : sevasai@mahadiscom.in

SE/VC/Tech/UE/

Dated:

No 0 5 9 0 1

2 0 OCT 2010

To,
The Web master Team.

Sub: Regarding Publication of Advertisement on Mahadiscom web Home
Page for Allocation of work by lottery System to Unemployed
Engineer in Virar Division Vasai Circle.


- 1) Sanction of Estimate for replacement of old rusted 1 L.T pole at Nawale Under Nirmal Section, Nalasopara West Sub-Division, Tal.Vasai, Dist.Palghar.
- 2) Sanction of Estimate for replacement of 1 no of HT Pole at Vinayak Appt,anchor Park,Achole 2 B Section, Achole Sub-Division,Tal:Vasai,Dist: Palghar.
- 3) Sanction of Estimate for replacement of 5 rusted L.T.Poles at Soaz All Under Nirmal Section,Nalasopara West Sub-Division,Tal:Vasai,Dist:Palghar.
- 4) Sanction of Estimate for replacement of Old rusted 3 L.T.Poles and deteriorated Conductor at Satko wadipadhal Shidiwadi,Shrikhandi under Umrle Section Nalasopara West sub Division,Tal:Vasai,dist:Palghar.
- 5) Sanction of Estimate for replacement of 1 no of HT Pole at Shivshankar Pada Under Nirmal section,Nalasopara West Sub-Division,Tal:Vasai,Dist:Palghar.
- 6) Sanction of Estimate for replacement of 3 bent L.T.Pole and deteriorated conductor at Khardi on 4706328 under Virar Rural Section,Virar East Sub-division,Tal:Vasai,Dist:Palghar.
- 7) Sanction of Estimate for replacement of 3 bent L.T.Pole and deteriorated conductor at Ghasspada on 4706389 under Virar Rural Section,Virar East Sub-Div ,Tal:Vasai,Dist:Palghar.
- 8) Sanction of Estimate for replacement of 3 rusted L.T.Pole and deteriorated conductor at Koparil on 4706303 under Virar Rural Section,Virar East Sub-Division,Tal:Vasai,Dist:Palghar.
- 9) Sanction of Estimate for replacement of 2 bent L.T.Pole and deteriorated conductor at Vaitarana on 4706325 under Virar Rural Section,Virar East Sub-Div ,Tal:Vasai,Dist:Palghar.
- 10) Sanction of Estimate for replacement of 9 L.T.Pole at Nirmalkalamb under Nirmal section Nalasopara West Sub-Div ,Tal:Vasai,Dist:Palghar.
- 11) Sanction of Estimate for replacement of 6 L.T.Pole at Mamavati Tempal ,Hunganbhat Vatar Rajodi Church under Vatar section Nalasopara West Sub-Div ,Tal:Vasai,Dist:Palghar.
- 12) Sanction of Estimate for replacement of old rusted 3 L.T.Pole at Bhulgaon,Wagholi , under Nirmal section Nalasopara West Sub-Div ,Tal:Vasai,Dist:Palghar.
- 13) Sanction of Estimate for replacement of old rusted 3 H.T.Pole at Nankarpada , under Parol section Virar East Sub-Div ,Tal:Vasai,Dist:Palghar.

- 14) Sanction of Estimate for replacement of old rusted 2 Bent L.T.Pole and deteriorated Conductor at Garelpada under Santosh Bhavan section , Nalasopara East Sub-Div ,Tal:Vasai,Dist:Palghar.
Amt upto Rs10 Lakhs only.

Above work is to be allotted by lottery System to Unemployed Engineer in Virar Division Vasai Circle.

Date of Lottery: 01.11.2018
Time: 3.00 PM

Venus: Office of the Superintending Engineer, 2/3 "Deepashree" Navghar(E), Vasai Rd.
The Unemployed Engineer who is registered with Vasai Circle Virar Division only is requested to atten along with paid money receipt copy.


Superintending Engineer
Vasai Circle