



MAHARASHTRA STATE ELECTRICITY DISTRIBUTION CO. LTD.

[Formerly Maharashtra State Electricity Board]

Phone: 26474211 / 26472131

CIN No:- U40109MH2005SGC153645

Fax: 91 22 26473429

Email-cestores@mahadiscom.in

Material Management Cell,
Prakashgad, 1st Floor,
Bandra (East),
Mumbai-400051.

Ref. No. CE/MMC/MSC/

001608

Date: 09 MAY 2016

To,

The Chief Engineer,

MSEDCL,

O & M Zone, Kalyan / Latur / Nanded / Nashik / Jalgaon / Baramati / Amravati / Aurangabad / Bhandup /Konkan /Kolhapur /Pune/ Akola /Gondia/Chandrapur /Nagpur.

Sub: Urgent Repairing of failed Dist. T/F from Transformer lying at repairers and filter unit.

Ref: I) ED(Dist-II)/439 Dt 25.2.2016, The letter from Executive Director (Dist-II)

II) Circular SP/GR.XII/4558 dt 16.11.15


III) ED(Dist-II)/1493 Dt 04.05.2016, The letter from Executive Director (Dist-II)

In connection with the above this is to state that the review of failed transformer, balance to replaced, T/F laying with repairer, at site & filter unit, has taken by the competent authority. Zone wise status of failed T/F laying at various location as on 12-05-2016 is as below.

Sr. No.	Name of Zone	Failed Transformers lying at Various locations as on 12-05-2016						Total	
		No. of T/f lying with repair agency		No. of T/f lying at site		No. of T/f lying at filter units			
		63 kVA	100 kVA	63 kVA	100 kVA	63 kVA	100 kVA	63 kVA	100 kVA
1.	Bhandup	0	7	0	0	8	22	8	29
2.	Kalyan	100	100	39	19	367	383	506	502
3.	Konkan	17	15	36	19	236	175	289	209
4.	Kolhapur	128	129	16	31	304	127	448	287
5.	Latur	406	211	24	13	396	133	826	357
6.	Nanded	398	148	10	10	18	9	426	167
7.	Nashik	296	172	47	37	443	217	786	426
8.	Jalgaon	627	340	5	4	138	45	770	389
9.	Pune	68	94	22	23	316	209	406	326
10.	Baramati	239	208	9	4	258	162	506	374
11.	Akola	322	132	115	142	426	26	863	300
12.	Amravati	196	81	5	5	153	136	354	222
13.	Aurangabad	332	367	0	0	448	333	780	700
14.	Gondia	106	84	0	0	225	151	331	235
15.	Chandrapur	71	40	60	51	131	141	262	232
16.	Nagpur	269	186	30	37	384	217	683	440

Vide the letter referred above, you are already directed to get all the failed T/F repaired ,which are laying with repairer, site & filter unit in the month of May-2016, by taking personal effort, with aggressive follow up with repairer. Unfortunately the speed with which failed T/F are getting repaired is very slow & there is no personal intervention at your end.

As such , you are here by once again directed to look in the matter seriously & get all the failed T/F repaired which are lying with repairer / filter unit/ site in this month only, and maintain reservoir of repaired T/F's per Circle /District to meet emergent situation if any as directed.


Chief Engineer (M.M.Cell)

Copy s.w.r.t:- Director (Operations)/ Director (Projects), MSEDCL, Corporate Office, Mumbai.
Executive Director (Dist-II), MSEDCL, Corporate Office, Mumbai.

Copy to:- 1) The Chief Engineer, M.M.Cell, MSEDCL, Mumbai
2) OSD to Hon'ble Chairman & Managing Director, MSEDCL, Corporate Office, Mumbai.